

# vertisol

# CONSTELLATION



VISUAL CONTACT OUTSIDE



COLD

COLD-CUT, CRUSH-CUT OR  
ULTRASONIC



MANUFACTURED IN THE EU

## TECHNICAL PROPERTIES

| Fabric Characteristic       | Standard  |                                  |
|-----------------------------|---|----------------------------------|
| Composition                 |   | 84.5 % PVC + 15 % PES + 0.5 % PA |
| Weight (g/m <sup>2</sup> )  |   | 500 ± 5 %                        |
| Thickness (mm)              |   | 0.53 ± 5 %                       |
| Openness factor (%)         | Internal method   | Approximately 9 %                |
| Light fastness              | EN ISO 105 B02:2002<br>interior(blue scale level)   | 8<br>7 white                     |
| Tearing resistance (daN)    | EN ISO 13937-3:2001   | 6.2(Warp)/ 5.3 (Weft)            |
| Breaking strength (daN/5cm) | EN ISO 13934-1:1999   | 149.9 (Warp)/ 129.6 (Weft)       |
| Stretch (%)                 | EN ISO 13934-1:1999   | 22.4 (Warp)/ 21.9 (Weft)         |
| Recycled content            |   | 2% Pre-consumer                  |
| Antibacterial activity      | ASTM 2180-018   | Microorganism growth inhibition  |
| Roll size                   |   | Width 250 cm, Length 18 m        |
| Printable                   |   | Yes                              |
|                             |   | Indoor use only                  |
| Manufacturing properties    | <ul style="list-style-type: none"><li>○ Always store rolls horizontally</li><li>○ Cold-cut, crush-cut or ultrasonic</li><li>○ Welding: Thermo or ultrasonic</li><li>○ Manufacturing direction: Blinds must not be manufactured railroaded</li></ul>   | ↓                                |
| Maintenance                 | <ul style="list-style-type: none"><li>○ Periodic maintenance: remove dust with vacuum cleaner, dry cloth or compressed air</li><li>○ In case of accumulated dirt, it can be cleaned using a sponge or soft brush dipped in soapy water or spray cleaner. In Both cases the fabric should be rinsed, leaving the curtain to dry open</li><li>○ Under no circumstances should solvents or abrasives that could damage the fabric coating be used, so care should be taken to avoid paint, varnish or ink stains</li></ul> |                                  |

## Range of colours 2022

White Silver



Roller and Panel blinds

All specifications are based on average values and may deviate. The values are given for guidance and are not contractual. Subject to technical modifications.

# vertisol

VERTISOL INT'L SRL  
C-17, KM 18.92  
08403 Granollers  
SPAIN  
T: + 34 93 840 1444  
www.vertisol.com



ISO 9001:2015 and  
ISO 14001:2015  
certified company